



型式_Model	A	B	C
PL-HLDL3-1350-HO	1354	(451.5)	(451)
PL-HLDL3-1500-HO	1504	(501.5)	(501)
PL-HLDL3-1650-HO	1654	(551.5)	(551)
PL-HLDL3-1800-HO	1804	(601.5)	(601)

本製品は偏光フィルムと保護板の間に気泡が発生する可能性があります。
 This product there is a possibility you to bubble protection plates and the polarizing film that occurs.
 偏光フィルムは2カ所の継ぎ目が有ります。
 Polarizing film has two seams.

UNIT:mm

REVISION	DATE	DESCRIPTION	REVISED
000			

ISSUE DATE	SCALE	APPROVED	NAME
2021/10/29	1:2	T.OSAWA	PL-HLDL3-1800-HO
 CCS Inc.	SHEET SIZE	CHECKED	DRAWING NAME
	A4	Y.INOUE	外観図_Outline
	DESIGNED	H.TOYOTA	DRAWING No.
PROJECTION		DRAWN	REVISION SHEET
		H.TOYOTA	000 01/01
			UA39439-G